1/26/04

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS


The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I,	Gene	eral Information
	4.	Report Time Period: From (mo./yr.) 1/2003 To (mo./yr.) 12/2003
	2.	DOGM File Number (Mine No): M /035/020
	3.	Mine Name: Lake view Rock Beck Street Quarry
	4	Mineral(s) Mined (or permitted to mine):
	5.	Type of mine Surface Mine or Underground Mine
	6.	Legal Description (Location of Lands Affected):
		1/4,1/4, Section 13. Township 11. Range 1 W
		1/4,1/4, Section 14, Township 1 N, Range 1 W
		1/4,1/4, Section, Township, Range
7.	Nam	e of Operator or Company: Lakeview Kock Products, Inc.
	8.	Permanent Street Address: P.O. Box 516760
		City, State, Zip: North Salt Lake, Utah 84054
		Phone: 801-292-7161 Fax: 801-295-0530
	9.	Company Representative (or designated operator):
		Name: Kussell A. Larsen
		Title: U.P.
		Business Address: P.O. Box 540700
		City, State, Zip: NSL, Utah 84654
		Phone: 961-292-7161 Fax: 861-295-0530
		Please check if any of the above information has changed since previous year.
II.	<u>Mini</u>	ng and Reclamation RECEIVED
	1.	Was there any mine related activity during the past year? Yes ▼ No □ JAN 2 1 2004
	2.	If no - what was the last year of activity?
	3.	If yes - how much ore or mineral was mined? 788.586 tous

- 1 -

4.	additional surface disturbances that occurred during the past year.			
	crushed soud and group			
	materials.			
5.	How much additional acreage was disturbed during the past year?			
6.	How much acreage was reclaimed during the past year?			
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.			
8.	What is the total disturbed acreage of entire project at years end? 82.6 acre 5			
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year.			
·	Continue mining the face to the			
	East.			
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .			
III. <u>Additional</u>	<u>Information - R647-4-121.2 and .3</u>			
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.			
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.			
IV. <u>Signature</u>	Requirement			
I here	by certify that the foregoing is true and correct.			
	Name (Typed or Print):			
	Title of Operator:			
	Signature of Operator:			
	Date: 1-16-04			

jb o:\forms\reports\MR-AR



- 1 PROPERTY LINE SHOWN IS LOCATED FROM EXISTING RECORD DATA AND IS PLACED AS A BEST FIT. LOCATION DOES NOT REFLECT AN ACTUAL PROPERTY 2 SURVEY MAP IS COMPILED FROM PHOTOGRAPHY DATED MARCH 24, 2003
 3 MAPPING WAS DESIGNED TO REFLECT THE GENERAL TOPOGRAPHY AND MAY OR
- MAY NOT MEET NATIONAL MAP ACCURACY STANDARDS

LAKEVIEW ROCK PRODUCTS, INC. BECK STREET QUARRY

FIGURE 3 FACILITY MAP

ibr			DATE 12/30/03
environmental const	ltants, inc	C. Elko, Hevado Boins, Idaho	NOISIS
DESIGN LM DRAWN CP	CH'D BY	SCALE 1"=400'	RE S

